Wireless Tally System Firmware Upgrade

1. Firmware Version Records

Released date	Firmware Version	Release Log	Download Link
2024.04.12	S4.0.0.4	● Update to support BMD ATEM Mini	https://download-hollyland.oss-us-east-1.aliyuncs.com/Firmware/Wireless_Intercoms/5005/Wireless%20Tally_H100_S4.0.0.4.zip

2. Updating Guide

2.1 Kindly Note:

- **It takes the risk to update the firmware, please avoid updating the firmware when the device is used for the important events**
- **Please feel free to contact our technical support engineer if the updating failure or error causes the malfunction of the device: Support@hollyland.com**
- **When the device original firmware version is 3.0.0.1, then pls drag the firmware to upgrade.**

2.2 Updating Tool

- one computer with Windows or Mac OS
- one USB flash disk which is under 32G storage （FAT32 format）
- One USB Type-C cable

2.3 Operation Steps

2.3.1 Upgrade with USB disk

a. Download the firmware file, and prepare one USB disk with USB-A port which memory less than 32GB.
b. Plug the USB disk into laptop, format the USB disk to FAT32，put the upgrade firmware "HLD_15_FP_H100_S4.0.0.4.ota" into the root directory of the USB disk (make sure only one firmware inside，please do not put it inside of any folder)
c. Plug the USB disk into tally base station via USB-A port , the tally base station will reboot automatically after upgraded

2.3.2 Upgrade with laptop

2.3.2.1 Upgrade with APP

a. Download the firmware file
b. Connect the base station via USB-C port with laptop
c. Open the corresponding app for upgrade.("I5005_IPC_MAC_EN_v3.0.0.0.1.app" for mac OS,"I5005_IPC_EN_v3.0.0.0.1.exe" for Windows)

2.3.2.2 Drag the firmware to upgrade

a. Download the firmware file
b. Connect the base station via USB-C port with laptop
c. Drag the firmware "HLD_15_FP_H100_S4.0.0.4.ota" into the device that recognized as one USB disk by laptop